

## NX Shortcut Keys

File-New	Ctrl+N
File-Open	Ctrl+O
File-Save	Ctrl+S
File-Save As	Ctrl+Shift+A
File-Plot	Ctrl+P
File-Execute-Grip	Ctrl+G
File-Execute-Debug Grip	Ctrl+Shift+G
File-Execute-NX Open	Ctrl+U
Edit-Undo List	Ctrl+Z
Edit-Redo	Ctrl+Y
Edit-Cut	Ctrl+X
Edit-Copy	Ctrl+C
Edit-Paste	Ctrl+V
Edit-Delete	Ctrl+D
Edit-Selection-Top Selection Priority - Feature	Shift+F
Edit-Selection-Top Selection Priority - Face	Shift+G
Edit-Selection-Top Selection Priority - Body	Shift+B
Edit-Selection-Top Selection Priority - Edge	Shift+E
Edit-Selection-Top Selection Priority - Component	Shift+C
Edit-Selection-Select All	Ctrl+A
Edit-Object Display	Ctrl+J
Edit-Show and Hide-Show and Hide	Ctrl+W
Edit-Show and Hide-Immediate Hide	Ctrl+Shift+I
Edit-Show and Hide-Hide	Ctrl+B
Edit-Show and Hide-Show	Ctrl+Shift+K
Edit-Show and Hide-Show All	Ctrl+Shift+U
Edit-Show and Hide-Invert Shown and Hidden	Ctrl+Shift+B
Edit-Move Object	Ctrl+T
View-Operation-Fit	Ctrl+F
View-Operation-Zoom	Ctrl+Shift+Z
View-Operation-Rotate	Ctrl+R
View-Section-Edit Section	Ctrl+H
View-Visualization-Ray Traced Studio	Ctrl+Shift+W
View-Visualization-High Quality Image	Ctrl+Shift+H
View-Layout-New	Ctrl+Shift+N
View-Layout-Open	Ctrl+Shift+O
View-Layout-Fit All Views	Ctrl+Shift+F
View-Information Window	Ctrl+Shift+S
View-Current Dialog Box	F3
View-Move Clip Left	Shift+F1
View-Move Clip Right	Shift+F2
View-Full Screen	Alt+Enter
View-Maximize Resource Bar Tab	F11

View-Reset Orientation	Ctrl+F8
Format-Layer Settings	Ctrl+L
Format-WCS-Display	W
Finish Sketch	Ctrl+Q
Extrude	X
Normal View to Sketch	Shift+F8
Move in an Orthographic Direction	Drag+Shift
Copy in Another Position	Drag+Ctrl
Copy Along an Orthographic Direction	Drag+Shift+Ctrl
Tools-Expressions	Ctrl+E
Tools-Journal-Play	Alt+F8
Tools-Journal-Edit	Alt+F11
Tools-Macro-Start Record	Ctrl+Shift+R
Tools-Macro-Playback	Ctrl+Shift+P
Tools-Movie-Record	Alt+F5
Tools-Movie-Pause	Alt+F6
Tools-Movie-Stop	Alt+F7
Tools-Customize	Ctrl+1
Information-Object	Ctrl+I
Analysis-Curve-Refresh Curvature Graphs	Ctrl+Shift+C
Preferences-User Interface	Ctrl+2
Preferences-Visualization	Ctrl+Shift+V
Preferences-Selection	Ctrl+Shift+T
Preferences-Object	Ctrl+Shift+J
Application-Modeling	Ctrl+M
Application-Shape Studio	Ctrl+Alt+S
Application-Drafting	Ctrl+Shift+D
Application-Manufacturing	Ctrl+Alt+M
Application-Inspection	Ctrl+Alt+I
Application-Sheet Metal-Sheet Metal	Ctrl+Shift+M
Application-PCB Design-Flexible Printed Circuit Design	Ctrl+Alt+P
Help-On Context	F1